

Oil Field Environmental Incident Summary

Incident: 20160128164240 **Date/Time of Notice:** 01/28/2016 16:42
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: CCU BURNER CTB
Field Name: CORRAL CREEK **Well File #:**
Date Incident: 1/27/2016 **Time Incident:** 17:00 **Facility ID Number:** 416647-04
County: DUNN **Twp:** 147 **Rng:** 95 **Sec:** 24 **Qtr:** SW SW
Location Description: Immediately adjacent to the SE side of the production facility pad.

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
600 N. DAIRY ASHFORD
HOUSTON, TX 77079

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident: Fire

	Spilled	Units	Recovered	Units	Reported to NRC:	No	Followup	Units
Oil	0.5	Barrels						
Brine								
Other								

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/3/2016 **Clean Up Concluded:** 2/2/2016

Risk Evaluation:

Fire was extinguished. No further risk remains.

Areal Extent:

The oil sprayed an area approx. 120 yds by 26 yds. approx 10 yds by 30 yds was burned in grass fire.

Potential Environmental Impacts:

None.

Action Taken or Planned:

The fire was extinguished and the affected production facility was shut down. Oil impacted gravel on the pad will be collected for appropriate management. We will work with the property owner to address potential oil impacted vegetation and soil off of the pad.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/28/2016 ***Status:*** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted area off location. Follow-up is required.

Date: 2/4/2016 ***Status:*** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 10:45. 23 degrees F, SW wind 15-25 mph, sunny. It appeared that the release occurred toward the SE of the CTB where an area approximately 60' by 30' had been disturbed by equipment and showed new soil/gravel/scoria placed. Some oil staining appeared on soils showing within the new soils. Photos were taken of the location which is in Section 23, not 24 as the report shows. More followup needed.